

FOT (Fixed Orifice Tube) Assembly Proper Installation Quality Alert - 3July03




Figure 1: **PROPERLY** seated FOT Assembly against the Aluminum tube crimp.




Figure 2: **IMPROPERLY** seated FOT Assembly against the Aluminum tube crimp.




Figure 3: FOT Assembly moves rapidly into the tube crimp during the evacuation and fill process or during high compressor loads and pressure. The brass tube will continue to move out of position. A/C system may not function properly due to flow restrictions.